



**Photograph 31. Ghost Lake outflow at old rail bed, looking south (6 Sept 2007)**



**Photograph 32. Wetland at end of existing drill road (6 July 2010)**



**Photograph 33. Wetland at end of existing drill road (6 July 2010)**



**Photograph 34. Lichen and sphagnum to east of Lalor site (6 July 2010)**



**Photograph 35. Lichen and sphagnum to east of Lalor site (6 July 2010)**



**Photograph 36. Deep sphagnum to east of Lalor site, black spruce canopy (6 July 2010)**



**Photograph 37. Lichen cover on bedrock outcrop (6 July 2010)**



**Photograph 38. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 39. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 40. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 41. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 42. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 43. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 44. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 45. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 46. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**





**Photograph 47. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 48. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 49. Panoramic of cleared Lalor site, numerous bedrock ridges (6 July 2010)**



**Photograph 50. Bedrock and lichen south of site (6 July 2010)**



Photograph 51. Drill road off south side of site (6 July 2010)



Photograph 52. Open canopy and treed rock to south side of Lalor site (6 July 2010)



**Photograph 53. Treed muskeg to south side of Lalor site (6 July 2010)**



**Photograph 54. Grasses at cleared drill site at end of existing drill road (6 July 2010)**




**Photograph 55. Vegetation along disturbed area of Lalor access road (6 July 2010)**



**Photograph 56. Drill road to north of cleared alignment (6 July 2010)**



Photograph 57. Disturbed area to north of Lalor access road alignment (6 July 2010)



Photograph 58. Vegetation downstream of culvert crossing 1 (former drill road) (6 July 2010)



**Photograph 59. Vegetation upstream of culvert crossing 1 (former drill road) (6 July 2010)**



**Photograph 60. Vegetation downstream of culvert crossing 1 (former drill road) (6 July 2010)**



**Photograph 61. Culvert crossing 1 (Lalor access road) (6 July 2010)**